



SITE VEHICLE SIGNAGE GENERAL NOTES

- 1. AT ALL SITE VEHICLE SIGNAGE WITH "BLUE COLORED" STRUCTURAL FRAMES, THE "BLUE COLORED" STRUCTURAL FRAMES SHALL BE REPAINTED.
- 2. ALL REPAINTING SHALL BE PERFORMED PER THE REQUIREMENTS OF THE CONTRACT DOCUMENTS SUCH AS THE EXISTING CONDITIONS SHALL BE PROPERLY PREPARED FOR NEW PAINT.
- 3. QUANTITY OF SIGNS: 15

© 2024 CALDWELL ASSOCIATES ARCHITECTS, INC

SIGN SHALL REMAIN —— UNDISTURBED TYPICAL


AT EXISTING SITE VEHICLE SIGNAGE THE "BLUE COLORED" STRUCTURAL FRAMES SHALL BE REPAINTED TYPICAL



















ALL EXISTING EXTERIOR STUCCO SURFACES THROUGHOUT THE ENTIRE SCHOOL BUILDING SHALL BE REPAIRED AND REPAINTED


POWER WASH ALL ALUMINUM WALKWAY — COVERED SURFACES THAT ARE EXPOSED TO VIEW




REPAINT EXISTING STUCCO AFTER STUCCO REPAIRS. COLOR TO MATCH EXISTING BLUE COLOR. ALL GRAPHICS SHALL BE REPAINTED ONTO THE COLUMNS MATCHING THE EXISTING GRAPHICS. GRAPHIC PAINTING SHALL BE PERFORMED BY A PAINTING SUBCONTRACTOR WITH EXPERIENCE PERFORMING GRAPHIC PAINTING WORK



- ALL EXISTING EXTERIOR STUCCO SURFACES THROUGHOUT THE ENTIRE SCHOOL BUILDING SHALL BE REPAIRED AND REPAINTED





NO. 21 - EXISTING STUCCO AND EIFS - REPAIRS AND RESURFACING . ALL EXISTING STUCCO SHALL BE REPAIRED AND RESURFACED PER SPECIFICATION '07 24 82	NO. 24 - MECHANICAL ROOMS - NEW OPENINGS IN EXISTING CMU WALLS FOR RETURN AIR O
 PORTLAND CEMENT PLASTER (STUCCO) REPAIR AND RESURFACING' ALL EXISTING EIFS SHALL BE REPAIRED AND RESURFACED PER SPECIFICATION '07 24 83 - EIFS REPAIR AND RESURFACING' SEE DRAWING SHEETS A321, A322, AND A323 FOR REFERENCE IMAGES. EXISTING STUCCO AND EIFS REPAIRS AND RESURFACING INCLUDES ALL EXISTING STUCCO AND EIFS CONDITIONS SUCH AS, BUT NOT LIMITED TO, EXTERIOR WALLS, PARAPETS, CANOPY COLUMNS, AND COURTYARD LOW MASONRY WALLS. 	CMU NEW HOLE SIZE CUT INTO CMU WALL VARIES. SEE MECHANICAL DRAWINGS FOR SIZES
IO. 26 - EXTERIOR INSULATION AND FINISH SYSTEM (EIFS) GENERAL NOTES	
1. 07 24 19 - WATER-DRAINAGE EXTERIOR INSULATION AND FINISH SYSTEM (EIFS): 2. 07 24 83 - EIFS REPAIR AND RESURFACING:	
THE FOLLOWING SHALL BE PROVIDED IN ADDITION TO THE REQUIREMENTS NOTED IN THE DRAWINGS AND SPECIFICATIONS.	
AT ALL EXISTING EIFS AND NEW EIFS CONDITIONS WHERE THE BOTTOM OF THE EIFS STARTS AT GROUND LEVEL THE FOLLOWING SHALL BE PROVIDED:	A de la
1) LAYER OF GLASS FIBER MESH REINFORCED MESH EQUAL TO THE FOLLOWING BASIS OF DESIGN RODUCTS SHALL BE INSTALLED IN A BASE COAT. PROVIDE FROM GROUND LEVEL TO A MAXIMUM IEIGHT OF 8'-0".	A Charles the
 a. STO ARMOR MAT XX - ULTRA-HIGH IMPACT RESISTANT, 20 OZ. PER SQ.YD. ALKALI RESISTANT GLASS-FIBER REINFORCING MESH. b. DRYVIT PANZER 20 - 20.5 OZ/YD2 	PHOTO FROM INSIDE MECHANICAL ROOM
6. (1) LAYER OF STANDARD MESH INSTALLED OVERTOP OF THE GLASS FIBER MESH REINFORCED MESH WITH BOTH MESHES BEING INSTALLED IN A BASE COAT. PROVIDE FROM GROUND LEVEL TO A	
MAXIMUM HEIGHT OF 8'-0". PROVIDE A SKIM COAT OF BASE COAT OVER THE INSTALLED MESHES TO PROVIDE A FLAT SURFACE.	PHOTOS ARE DURING RENOVATION WORK AND ARE AS-BUILT CONDITIONS AT LUCILLE MOORE ELEMENTARY SCHOOL
PROVIDE A FEATHER / FLOAT COAT OF THE BASE COAT FROM THE TOP OF THE NEW MESHES UP ONTO THE EXISTING EIFS SURFACES ABOVE FOR THE PURPOSE OF PROVIDING A SMOOTH VISUALLY CONCEALING TRANSITION FROM THE NEW EIFS TO THE EXISTING EIFS.	
IO. 22 - NOT USED	

EXISTING WATER HEATER TO BE

HIGH ON WALL ABOVE SINK.

THOROUGHLY CLEAN ROOM.


- EXISTING RUBBER WALL BASE

REPLACED

SHALL BE REMOVED AND NOT

REMOVED AND REPLACED WITH

NEW WATER HEATER MOUNTED




REPAINT ROOM. SEE NTERIOR FINISH SCHEDULE ON SHEET 1101 FOR CUSTODIAL/JANITORIAL ROOM INTERIOR FINISHES REQUIREMENTS

4 TYP JANITOR ROOM A101A N.T.S

NO. 09 NO. 12 **INTERIOR FACILITY CLEANING DEMOLITION - EXISTING RETRACTABLE WALL PARTITIONS** MARKER BOARDS (WHITE BOARDS) & TACKBOARDS 1. ALL MARKER BOARDS AND TACKBOARDS IN CLASSROOMS, RESOURCE CLASSROOMS, WHERE NOTED THE RETRACTABLE WALL PARTITION SYSTEMS AND ALL CONTRACTOR SHALL PROVIDE A THOROUGH INTERIOR CLEANING OF THE ENTIRE FACILITY AND COMPUTER LABS SHALL BE REMOVED, SALVAGED, AND DELIVERED TO THE ASSOCIATED HARDWARE SHALL BE REMOVED. EXCLUDING THE RELOCATABLE BUILDINGS. **OWNER'S MAINTENANCE STORAGE FACILITY.** THE CONTINUOUS WOOD BLOCKING ATTACHED TO THE BOTTOM OF THE ALL OTHER MARKER BOARDS AND TACKBOARDS SHALL REMAIN UNLESS SPECIFICALLY SINGLE-USE RESTROOMS TILE GROUT CLEANING EXISTING STEEL BEAM SHALL REMAIN. NOTED TO BE REMOVED. PATCH AND REPAIR EXISTING ADJACENT WALLS AND BULKHEADS TO REMAIN. AT ALL SINGLE-USE RESTROOMS ALL WALL AND FLOOR TILE GROUT SHALL BE THOROUGHLY WHERE MARKER BOARDS AND TACKBOARDS ARE REMOVED THE CONTRACTOR SHALL CLEANED SUCH AS REMOVING "GRIME & GRUNGE" APPEARANCES. THE "GRIME & GRUNGE" (DEMO-FWP) D. THE ENTIRE RETRACTABLE FOLDING WALL PARTITION SYSTEM LOCATED IN THE PATCH, REPAIR, AND FINISH WALL SURFACES. APPEARANCE TYPICALLY OCCURS AT THE WALL TILE AT THE BASE OF THE WALL. WHITE BOARD BASIS-OF-DESIGN PRODUCT DINING AND MULTIPURPOSE ROOMS SHALL BE REMOVED. THIS INCLUDES ALL 4.1. MANUFACTURER: CLARIDGE ASSOCIATED HARDWARE AND STORAGE CLOSET DOORS. JCT INTERIOR CLEANING 4.2. PERIMETER TRIM: 3/4" TO 1-1/2" WIDE PATCH AND REPAIR EXISTING ADJACENT WALLS & GYPSUM CEILING TO ALL EXISTING DUCTS THROUGHOUT THE ENTIRE SCHOOL SHALL BE PROVIDED WITH AN 4.3. MARKERBOARD: EQUAL TO CLARIDGE LCS MAGNETIC PORCELAIN INTERIOR DUCT CLEANING. THIS EXCLUDES THE RELOCATABLE CLASSROOM BUILDINGS. F. CREATE NEW STORAGE ROOM AT EXISTING SPACE WHERE THE FOLDING WALL 4.4. ACCEPTS MAGNETIC ACCESSORIES PARTITION WAS STORED. UARRY TILE DEEP CLEANING 4.5. MARKERBOARD COLOR: WHITE 4.6. CLEAR ANODIZE ALUMINUM FRAME THE CONTRACTOR SHALL PROVIDE A DEEP THOROUGH CLEANING OF ALL EXISTING QUARRY 4.7. 2" MAP RAIL WITH CORK TYPE TACK MATERIAL TILE (FLOOR & WALL TILE) THROUGHOUT THE ENTIRE CAFETERIA KITCHEN SUITE THAT 4.8. FULL LENGTH MARKER BOX TRAY INCLUDES THE KITCHEN SUPPORT ROOMS. 4.9. DIMENSIONS: SEE SCHEDULE CONTINGENCY ALLOWANCE - INSPECT & REPAIR EXISTING FLOOR AS NEEDED. PAY NEW INTERIOR METAL STUD GYPSUM WALLS 4.10. APPROXIMATE PANEL THICKNESS: 1/2" PARTICULAR ATTENTION TO HIGH TRAFFIC AREAS. THE BIDDER SHALL NOT INCLUDE COSTS NEW-WALL A. WHERE EXISTING RETRACTABLE WALL PARTITION SYSTEMS IN CLASSROOMS FOR ANY REPAIRS IN THE BID PRICE. THE COST OF ALL REPAIRS SHALL BE DETERMINED AND COMPUTER LABS ARE REMOVED, NEW METAL STUD GYPSUM WALLS TACKBOARD BASIS-OF-DESIGN PRODUCT DURING CONSTRUCTION AND PAID FOR FROM THE CONTINGENCY ALLOWANCE. HALL BE PROVIDED. 5.1. SEE SPECIFICATIONS SEE DRAWING SHEET A302 FOR MORE INFORMATION SUCH AS STC AILLWORK COUNTERS CLEANING MARKER BOARD QUANTITY: SEE ARCHITECTURAL FLOOR PLANS FOR SIZES AND ACOUSTICAL SOUND CONTROL REQUIREMENTS. 5. FOR ALL MILLWORK TO REMAIN, THE CONTRACTOR SHALL PROVIDE A DEEP THOROUGH SPECIAL NOTE: WHERE RETRACTABLE FOLDING WALL PARTITION SYSTEM IN CLEANING OF ALL EXISTING MILLWORK COUNTERTOPS TO REMOVE SIGNIFICANTLY QUANTITIES. THE CAFETERIA IS REMOVED A NEW WALL SHALL **NOT** BE PROVIDED. ADHERED SUBSTANCES AND MARKINGS. TACKBOARD QUANTITY: 7.1. SEE ARCHITECTURAL FLOOR PLANS FOR SIZES AND QUANTITIES. NTERIOR WOOD DOORS 7.2. SEE DRAWING "G/I105" AND ITEM 14 ON THIS SHEET FOR TACK STRIPS TO BE ALL INTERIOR WOOD DOORS SHALL BE THOROUGHLY CLEANED SUCH AS REMOVING ALL PROVIDED IN ALL CORRIDORS DIRECTLY CONNECTED TO CLASSROOMS. TAPING AND "STICKY" RESIDUES. PRIOR TO PURCHASING THE CONTRACTOR, OWNER, AND ARCHITECT SHALL CONFIRM SALVAGED MATERIALS DELIVERED TO NO. 10 THE SIZES AND INSTALLATION LOCATIONS WITH THE EXISTING CONDITIONS. OWNER'S OFFSITE STORAGE FACILITY **EXISTING RESCUE WINDOWS** ALL EXISTING ITEMS TO BE REMOVED, SALVAGED, AND DELIVERED TO THE OWNER'S OFFSITE NO. 13 STORAGE FACILITY SHALL BE DELIVERED TO THE ADDRESS BELOW. CONTRACTOR SHALL HAVE A WINDOW SUBCONTRACTOR FAMILIAR WITH THE TYPE OF ITEMS SHALL BE DELIVERED DURING THE OWNER'S MAINTENANCE DEPARTMENT'S NORMAL EXISTING "RESCUE WINDOWS" PERFORM AN INSPECTION OF ALL EXISTING WINDOWS TO INTERIOR SEALANTS WORKING HOURS. EVALUATE THE EXISTING CONDITIONS OF THE WINDOWS SUCH AS IF THE "RESCUE IF THE FACILITY IS NOT OPEN (UNLOCKED) AT THE TIME OF THE DELIVERY THE ITEMS SHALL WINDOWS" ARE OPERATING CORRECTLY. WINDOW SUBCONTRACTOR SHALL PROVIDE A AT MILLWORK BASE CABINETS COUNTERS TO REMAIN (AND WILL NOT BE NOT BE UNLOADED AND SET OUTSIDE OF THE STORAGE BUILDING - COORD W/ OWNER'S P.M. REPORT OF THE EXISTING CONDITIONS. REPLACED) REMOVE EXISTING SEALANTS AND INSTALL NEW SEALANTS AT THE FOLLOWING JOINT CONDITIONS. 4. 1140 WEST 17TH STREET, PANAMA CITY, FLORIDA NO. 11 **1.1. TRANSITION JOINT BETWEEN COUNTER TO ABUTTING WALLS** 1.2. TRANSITION JOINT BETWEEN COUNTER TO ABUTTING BACKSPLASHES FIRE EXTINGUISHERS AND CABINETS 1.3. TRANSITION JOINT BETWEEN TOP OF BACKSPLASH TO ABUTTING WALLS NO. 08b - EXTERIOR SEALANTS 1.4. COLORS SHALL MATCH OR BE AESTHETICALLY COMPATIBLE WITH MILLWORK SEE SHEET "G002 - LIFE SAFETY" FOR INFORMATION AND QUANTITIES. ALL EXISTING SEALANTS AND BACKER RODS AT EXTEROR MASONRY VENEER COLORS. ARCHITECT SHALL SELECT COLOR FROM MULTIPLE CONTROL JOINTS SHALL BE FULLY REMOVED AND REPLACED WITH NEW MANUFACTURERS' STANDARD COLORS. ALL EXISTING FIRE EXTINGUISHERS AND CABINETS SHALL BACKER RODS AND SEALANT. REMAIN. CLEAN, PREP & REPAINT ALL EXISTING CABINETS. ALL EXISTING SEALANTS AND BACKER RODS AROUND THE PERIMETER OF PROVIDE NEW SEALANTS AT ALL PLUMBING FIXTURES AT THE TRANSITION JOINT THE EXTERIOR WINDOWS AND EXTERIOR DOOR FRAMES SHALL BE REMOVED BETWEEN THE PLUMBING FIXTURE TO ABUTTING WALL. COLOR TO BE SELECTED AND REPLACED WITH NEW SEALANTS AND BACKER RODS. NEW-REC INSTALL NEW FIRE EXTINGUISHER CABINET. BY ARCHITECT FROM MULTIPLE MANUFACTURERS' STANDARD COLORS. THERE ARE NO NEW FIRE EXTINGUISHER CABINETS.

A101A N.T.S.

0-



NO. 19 - DOWNSPOUT SPLASH BLOCKS

SHALL BE PROVIDED

1. A QUANTITY OF (15) CONCRETE SPLASH BLOCKS 18" WIDE BY 36" LONG


- NEW STEEL ANGLE MECHANICALLY BOLTED INTO


EXISTING CMU WALL AS SHOWN IN THE IMAGE


- NEW STEEL ANGLE IS NOT VISIBLE FROM

CLASSROOM SIDE OF WALL


EXISTING CMU WALLS FOR RETURN AIR GRILLES











Ð	EXISTING WALL MOUNTED SPEAKER - SEE ELECTRICAL			
(DEMO-RWP)	DEMO RETRACTABLE WALL PARTITION. SEE SHEET A101A AND A302			
NEW-WALL	NEW WALL. SEE SHEET A101A AND A302			
NEWLEC	-SEE SHEET A101 FOR DESCRIPTION THERE ARE NO NEW FIRE EXTINGUISHER CABINETS			
CUBBIES	EXISTING CUBBIES SHALL BE PERMANENTLY REMOVED. OWNER WILL PROVIDE NEW CUBBIES AS FURNITURE			
MWRMN	EXISTING MILLWORK AND WOOD SHELVING SHALL REMAIN AND SHALL BE THOROUGHLY CLEANED			
MWRPLCD	EXISTING MILLWORK SHALL BE REMOVED AND REPLACED WITH NEW MILLWORK			
ECH	EXISTING ELECTRICAL AND DATA VERTICAL WALL CHASE			
MB TB	NEW MARKER BOARD NEW TACK BOARD			
TBV	NEW 60" LENGTH X 36" HEIGHT TACK BOARD AT CLASSROOM VESTIBULE LOCATED ABOVE NEW OWNER PROVIDED CUBBIES. BOTTOM OF TACK BOARD AT 5'-6" ABOVE FINISH FLOOR. PRIOR TO PURCHASING COORDINATE WITH NEW OWNER PROVIDED CUBBIE FURNITURE			
TCH-TV	TEACHING TV: SHALL BE TEMPORARILY REMOVED AND SAFELY SECURELY STORED IN A CONDITIONED SPACE. EXISTING MARKER BOARD BEHIND TEACHING TV SHALL BE PERMANENTLY REMOVED.			



















BUILDING 2 KEY PLAN **BUILDING 1**

NO SCALE

DO NOT SCALE DRAWINGS







- SEE SHEET A601 FOR NEW FLASHING

PLAN LEGEND

E)	EXISTING WALL MOUNTED SPEAKER - SEE ELECTRICAL
(DEMO-RWP)	DEMO RETRACTABLE WALL PARTITION. SEE SHEET A101A AND A302
NEW-WALL	NEW WALL. SEE SHEET A101A AND A302
NEWKEEC	-SEE SHEET A101 FOR DESCRIPTION THERE ARE NO NEW FIRE EXTINGUISHER CABINETS
CUBBIES	EXISTING CUBBIES SHALL BE PERMANENTLY REMOVED. OWNER WILL PROVIDE NEW CUBBIES AS FURNITURE
MWRMN	EXISTING MILLWORK AND WOOD SHELVING SHALL REMAIN AND SHALL BE THOROUGHLY CLEANED
MWRPLCD	EXISTING MILLWORK SHALL BE REMOVED AND REPLACED WITH NEW MILLWORK
ECH	EXISTING ELECTRICAL AND DATA VERTICAL WALL CHASE
MB TB	NEW MARKER BOARD NEW TACK BOARD
TBV	NEW 60" LENGTH X 36" HEIGHT TACK BOARD AT CLASSROOM VESTIBULE LOCATED ABOVE NEW OWNER PROVIDED CUBBIES. BOTTOM OF TACK BOARD AT 5'-6" ABOVE FINISH FLOOR. PRIOR TO PURCHASING COORDINATE WITH NEW OWNER PROVIDED CUBBIE FURNITURE
TCH-TV	TEACHING TV: SHALL BE TEMPORARILY REMOVED AND SAFELY SECURELY STORED IN A CONDITIONED SPACE. EXISTING MARKER BOARD BEHIND TEACHING TV SHALL BE PERMANENTLY REMOVED.










IMAGE 5A



"FLASHING INFILL" BETWEEN GUTTERS AND METAL WALL PANELS A121 NOT-TO-SCALE










IMAGE 5B








DO NOT SCALE DRAWINGS















5	REF
-	NOT-TO-S




A301 NOT-TO-SCALE



















DEMO CHASE -EXISTING WALL CABINETS ----TO BE REMOVED EXISTING SINK CABINET AND COUNTER/BACKSPLASH TO BE REMOVED

> EXISTING WALL CABINETS TO BE REMOVED REMOVE EXISTING COUNTERTOP AND BACKSPLASH AND ANY

COUNTERTOP SUPPORT

EXISTING SINK CABINET AND COUNTER/BACKSPLASH TO BE

EXISTING WALL CABINETS -TO BE REMOVED


EXISTING RANGE HOOD TO BE PERMANENTLY REMOVED AND DELIVERED TO THE OWNER.

REMOVE EXISTING RANGE OUTLET AND ASSOC WIRING - SEE ELEC REMOVE EXISTING COUNTERTOP

AND BACKSPLASH AND ANY COUNTERTOP SUPPORTS ADJACENT EXISTING RANGE TO BE

PERMANENTLY REMOVED AND DELIVERED TO THE OWNER.

EXISTING SINK CABINET AND COUNTER/BACKSPLASH TO BE



1A CLASSROOM 1-100 A310 N.T.S.



EXISTING WALL CABINETS —

TO BE REMOVED

DEMO CHASE 🦟

EXISTING WALL CABINETS -TO BE REMOVED

EXISTING SINK CABINET AND

EXISTING SINK CABINET AND -

COUNTER/BACKSPLASH TO BE

REMOVED, CAP OFF PLUMBING IN

COMPLIANCE WITH BUILIDNG CODES

REMOVED

COUNTER/BACKSPLASH TO BE

REMOVE EXISTING CUBBIES -----

EXISTING SINK CABINET AND COUNTER/BACKSPLASH TO BE REMOVED








- DEMO CHASE ----EXISTING WALL CABINETS -TO BE REMOVED EXISTING RANGE HOOD TO BE -
- DELIVERED TO THE OWNER. REMOVE EXISTING RANGE OUTLET AND ASSOC WIRING - SEE ELEC

PERMANENTLY REMOVED AND

- DELIVERED TO THE OWNER.
- EXISTING SINK CABINET AND COUNTER/BACKSPLASH TO BE

REMOVED

REMOVE EXISTING COUNTERTOP AND BACKSPLASH AND ANY COUNTERTOP SUPPORTS ADJACENT TO RANGE








A310 N.T.S.


EXISTING SINK CABINET AND -COUNTER/BACKSPLASH TO BE REMOVED













A310 3/8" = 1'-0"




2A CLASSROOM 1-106 A310 N.T.S.



CLASSROOM 1-106

A310 3/8" = 1'-0" CLASSROOM 1-113 OPP

3A CLASSROOM 1-121







4A CLASSROOM 1-115



DO NOT SCALE DRAWINGS

A310





D	R	A	W	ļ	Ν	G	S



CALDWEL

SSOCIATES | ARCH

116 N TARRAGONA STREET, PENSACOLA, FL 32502


(850) 432 9500 | CALDWELL-ASSOC.COM


License No: AA26000721 | License No: IB0000995

PROJEC

VOLUME 1

U.







 3
 MEDIA SEC. 5-103

 A312
 3/8" = 1'-0"

2 CLINIC 1-149 A312 3/8" = 1'-0"

A312 3/8" = 1'-0"

- . Locations: Quantity (1) 2. Locations similar but opposite: NONE
- WALL CABINETS SHALL BE (PL-1)
 BASE CABINETS SHALL BE (PL-2)
- . COUNTERTOPS SHALL BE (PL-3)
- . REPLACE ALL MILLWORK WITH NEW MILLWORK MATCHING THE EXISTING MILLWORK CONFIGURATION.
- PRIOR TO BIDDING CONTRACTOR SHALL FIELD VERIFY EXISTING CONDITIONS


30" TALL BASE CABINET ____ 24" DEEP BASE CABINET


- 1. LOCATIONS: QUANTITY (1) 2. LOCATIONS SIMILAR BUT OPPOSITE: NONE
- 3. WALL CABINETS SHALL BE (PL-1) 4. BASE CABINETS SHALL BE (PL-2)
- 5. COUNTERTOPS SHALL BE (PL-3) 6. REPLACE ALL MILLWORK WITH NEW
- MILLWORK MATCHING THE EXISTING
- MILLWORK CONFIGURATION. PRIOR TO BIDDING CONTRACTOR SHALL FIELD VERIFY EXISTING CONDITIONS


LOCATIONS: QUANTITY (1) LOCATIONS SIMILAR BUT OPPOSITE: NONE

- WALL CABINETS SHALL BE (PL-1)
 BASE CABINETS SHALL BE (PL-2) . COUNTERTOPS SHALL BE (PL-3)
- REPLACE ALL MILLWORK WITH NEW
- MILLWORK MATCHING THE EXISTING MILLWORK CONFIGURATION. PRIOR TO BIDDING CONTRACTOR SHALL FIELD VERIFY EXISTING CONDITIONS

36"+/- TALL BASE CABINET; 24" DEEP BASE CABINET -


















ALL EXISTING STUCCO 🔫

REPAIRED AND

REPAINTED

AND EIFS SHALL BE



9 REF PHOTO #9

A321 NOT-TO-SCALE

A321 NOT-TO-SCALE

ALL EXISTING STUCCO AND EIFS SHALL BE **REPAIRED AND** REPAINTED





- REPLACE EXISTING SIGNAGE W/ NEW TO MATCH EXISTING, SEE SIGNAGE PLAN & NOTES
- CLEAN, PRIME AND PAINT EXISTING EXTERIOR DOOR & HOLLOW METAL FRAME, TYP ALL LOCATIONS PRESSURE WASH ALL BRICK VENEER TO REMOVE ALL DIRT, GRIME & DEBRIS, TYP ALL LOCATIONS



- INSPECT AND REPLACE DAMAGED METAL PARAPET CAP FLASHING, TYP ALL LOCATIONS
- PRESSURE WASH ALL BRICK VENEER TO REMOVE ALL DIRT, GRIME & DEBRIS, TYP ALL LOCATIONS CLEAN, PRIME AND PAINT **EXISTING EXTERIOR DOOR &** HOLLOW METAL FRAME, TYP ALL LOCATIONS PRESSURE WASH ALL ALUMINUM CANOPIES TO REMOVE ALL DIRT, GRIME &

23



18 REF PHOTO #18

- PRESSURE WASH ALL LUMINUM CANOPIES TO REMOVE ALL DIRT, GRIME & DEBRIS, TYP ALL LOCATIONS EAN, PRIME AND PAINT **EXISTING STUCCO, PATCH ALL** EXISTING STUCCO AS REQ'D., TYP ALL LOCATIONS
- REPLACE EXISTING SIGNAGE W/ NEW TO MATCH EXISTING, SEE SIGNAGE PLAN & NOTES
- PRESSURE WASH ALL BRICK VENEER TO REMOVE ALL DIRT, GRIME & DEBRIS, TYP ALL LOCATIONS
- CLEAN, PRIME AND PAINT **EXISTING EXTERIOR DOOR &** FRAME, TYP ALL LOCATIONS
- THOROUGHLY CLEAN ALL CANOPY DOWNSPOUTS, REMOVE ANY DEBRIS THAT MAY BE INSIDE, TYP ALL LOCATIONS





19 REF PHOTO #19 A321 NOT-TO-SCALE

- CAREFULLY PRESSURE WASH **CEILINGS AND REMOVE ALL** DIRT, GRIME & DEBRIS, TYP ALL LOCATIONS
- PRESSURE WASH ALL ALUMINUM CANOPIES TO **REMOVE ALL DIRT, GRIME &** DEBRIS, TYP ALL LOCATIONS
- PRESSURE WASH ALL BRICK VENEER TO REMOVE ALL DIRT, GRIME & DEBRIS, TYP ALL LOCATIONS



F
N



REF PHOTO #20 NOT-TO-SCALE

REMOVE ALL DIRT, GRIME & DEBRIS, TYP ALL LOCATIONS PRESSURE WASH ALL

POWDER COATED METAI FENCES TO REMOVE ALL DIRT, GRIME & DEBRIS, TYP ALL LOCATIONS PRESSURE WASH ALL BRICK VENEER TO REMOVE ALL

DIRT, GRIME & DEBRIS,

TYP ALL LOCATIONS - THOROUGHLY CLEAN ALL CANOPY DOWNSPOUTS, REMOVE ANY DEBRIS THAT MAY BE INSIDE, TYP ALL

LOCATIONS

PRESSURE WASH ALL ALUMINUM CANOPIES TO

- THOROUGHLY CLEAN ALL DOWNSPOUTS, REMOVE ANY

DEBRIS THAT MAY BE INSIDE.

PRESSURE WASH ALL BRICK

VENEER TO REMOVE ALL DIRT, GRIME & DEBRIS, TYP ALL LOCATIONS

REPAIR OR REPLACE AS REQ'D

EXISTING STUCCO, PATCH ALL EXISTING STUCCO AS REQ'D., TYP ALL LOCATIONS

CLEAN, PRIME AND PAINT

10 REF PHOTO #10 A321 NOT-TO-SCALE








CLEAN, PRIME AND PAINT **EXISTING EXTERIOR DOOR &** HOLLOW METAL FRAME, TYP ALL LOCATIONS - PRESSURE WASH ALL BRICK VENEER TO REMOVE ALL DIRT, GRIME & DEBRIS, TYP ALL LOCATIONS

REPLACE EXISTING SIGNAGE W/ NEW TO MATCH EXISTING, SEE SIGNAGE PLAN & NOTES


- PRESSURE WASH ALL ALUMINUM CANOPIES TO REMOVE ALL DIRT, GRIME & DEBRIS, TYP ALL LOCATIONS






- PRESSURE WASH ALL ALUMINUM CANOPIES TO **REMOVE ALL DIRT, GRIME &** DEBRIS, TYP ALL LOCATIONS


- CLEAN, PRIME AND PAINT EXISTING STUCCO, PATCH ALL EXISTING STUCCO AS REQ'D., TYP ALL LOCATIONS



11 REF PHOTO #11


16 REF PHOTO #16 A321 NOT-TO-SCALE










- CLEAN, PRIME AND PAINT EXISTING STUCCO, PATCH ALL EXISTING STUCCO AS REQ'D., TYP ALL LOCATIONS NEW PAINT COLORS SHALL MATCH THE EXISTING CONDITIONS COLORS AND PATTERN











- REMOVE EXISTING ALL WALL ANCHORS, FILL

TOMMY SMITH ES SHALL RECEIVE NEW METAL SOFFIT PANELING MATCHING THE METAL SOFFIT PANELING INSTALLED AT PATRONIS ES AS SHOW IN THE PICS







- REMOVE EXISTING ALL WALL ANCHORS, FILL HOLES WITH GROUT MATCHING EXISTING GROUT, AND RUB GROUT SMOOTH




- ALL PAPER TOWEL DISPENSERS IN ALL RESTROOMS SHALL BE REMOVED AND REPLACE WITH NEW SEE TOILET ACCESSORY SCHEDULE ON SHEET A303A




- INSTALL NEW TACK STRIPS






NOTE: CONTRACTOR TO FIELD VERIFY QUANTITY AND SIZES OF ALL EXISTING WINDOWS IN SCOPE OF WORK.



© 2024 CALDWELL ASSOCIATES ARCHITECTS, INC



_\___

